


St Hugh's Decoration Update

Pictures from Week 3




New energy efficient spot lights in the sanctuary ceiling



New ceiling tiles for the sanctuary with holes to allow smoke through




Repairs to the Confession Box walls



Live stream camera still in place



New frames for the sanctuary stained glass windows



Finishing off the new ceiling tiles & lights in the main body of the church



Finishing off the wall repairs ready for painting